Incoming Evaluation:	
	As necessary, fly to measure elevator average displacement out of stream, to log speeds, and to check rigging. Measure elevator asymmetry and trim asymmetry.
As i	necessary to correct for common mode out-of-stream:
[]	Remove stinger, rudder, and upper fin.
[]	Disconnect trim and raise horizontal empennage assembly onto maintenance stands.
[]	Inspect re lower fin re SB 112-56B or SB 114-12C.
[]	Inspect rudder spar re SL 114-17.
[]	Inspect stab aft attach fittings.
[]	Replace elevator push tube bearings as necessary.
	Modify stab forward attach fitting.
[]	Install stab incidence STC Doubler.
[]	Re-install stab at +1.5° AOA.
As necessary to correct for elevator asymmetry:	
[]	Remove elevators and elevator horn assembly.
[]	Inspect elevators i.a.w. AD 2011-07-13.*
[]	Replace elevator spars if cracked.*
[]	Install 44285-RE2 outboard hinge fittings if requested.*
[]	Weld horn assembly arm doublers onto elevator horn assembly.
[]	Jig elevators symmetry and match drill doublers.
[]	Re-install horn assembly and elevators to affirm elevator symmetry.
[]	Remove elevators and horn assembly, again.
[]	Strip, blast, prep, and paint horn assembly.
[]	Re-install horn assembly.
[]	Replace elevator hinge bushings and bearings as necessary.
	Re-install elevators and rig elevator deflections.
[]	Re-attach trim control, and re-rig trim tabs for symmetry and deflections.
[]	Fit, paint, and install STC stab root fairings.
Pre-Rig Evaluation, Rig, and Final Evaluation:	
[]	Rig gear doors and cowl flaps, reset aileron tabs, if any, to neutral.
[]	Fly to check rigging.
[]	Rig flaps, ailerons, and aileron tabs if any.
[]	Fly to log streamlining and speed results.
[]	File Forms 337 as necessary.

^{*} Extra charges may apply.